



AS-99 Anti-Spatter Compound

Product Description

An easily applied paste designed to prevent weld spatter build up on weld fixtures and other related equipment. AS-99 protects fixtures by forming a solid impenetrable film.

Typical Properties

Appearance Creamy White Paste
pH..... 10.0 – 10.4
Density 11.0 lbs/gallon

Application

Brush or roll on approximately 2-4 mils of this paste and allow 2 hours to dry between coatings.

Use Directions

Metal Mates AS-99 Anti-Spatter Compound is supplied ready to use. This material is recommended to be used on welding fixtures. Do not coat on tooling grounding points (gauge fixtures) that make ground contact between the metal component and the tooling for the weld operation. For easy removal of weld slag, simply use an air hose to blow slag off from the prepared surface and reapply AS-99 as necessary. If removal of AS-99 is required, it can be removed with a scraper, water and scrub brush, or pressure washer if entire fixture needs cleaning.

Safety and Handling

Avoid contact with eyes and prolonged contact with the skin. Wash thoroughly after handling. Minimum contact with this and all chemicals is a good policy to follow along with reading the Material Safety Data Sheet.

Storage

Indoor storage preferred. First in first out stock rotation is recommended. If frozen, allow to thaw then mix thoroughly.

Container Size

5 gallon pails, 55 gallon drums and 330 gallon totes.

TW **ROCOL® North America**

3624 West Lake Avenue · Glenview, IL 60026

Tel (800) 452-5823 · Fax (800) 952-5823

Tel (800) 657-5278 · Fax (800) 657-4897

www.rocolnorthamerica.com